

SECRETONT
51623**PRIORITY**

23 32Z

P 052317Z

FM CIA WASHDC

TO RUCSBR/SAC OFFUTT AFB, OMAHA, NEB

RUCVAB/4050TH STRAT WG, OL 19, BARKSDALE AFB, LA

RUEAHQ/DIAXX

RUECYG/NAVY PIC

RUWBCR/15TH AF, MARCH AFB, RIVERSIDE CAL.

RUNGAA/2D RTS, BARKSDALE, AFB LA.

DA GRNC

BT

SECRET

CITE CIA-Z-802

15TH AF (FOR DM4); SAC (FOR DIM, BRASS KNOB, DOCR, DM4). FROM
NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER.

1. CAMERA B 7 WAS USED IN MISSION 3682 FLOWN ON 2 AUGUST 1963;
PROCESSING WAS ACCOMPLISHED BY NAVY.

2. ORIGINAL NEGATIVE:

- A. THE EXPOSURE IS ADEQUATE AND THE RESOLUTION IS GOOD.
- B. 9R SIDE: BECAUSE OF A PROCESSOR MALFUNCTION, AN EMERGENCY
CUT WAS MADE AT FRAME 941 AND A 2" SWATH OF FILM REMOVED AND
PROCESSED BY HAND. THIS PIECE WAS OVERDEVELOPED AND SPLICED INTO

6 AUG 1963

HFS

CJS

CRG

TNS

ACL

Grace (File)

Declassification Review by NGA/DoD

SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification

1

THE ROLL. NO FURTHER DEGRADATION BECAUSE OF THIS MALFUNCTION WAS INCURRED.

C. 9L SIDE: SEVERAL ROWS OF MINUS DENSITY DOTS APPZAR AT ERRATIC INTERVALS ALONG THE MINOR AXIS OF THE FILM SPACED AT INTERVALS OF 1.55" ALONG THE MAJOR AXIS. THE FILM MIS-TRACKED IN THE CAMERA CONSISTANTLY CAUSING A WIDER THAN NORMAL BORDER ON THE OUTBOARD EDGE AND A LOSS OF 0.2" OF IMAGERY ON THE INBOARD EDGE.

D. FILM METERING WAS SLIGHTLY ERRATIC THROUGHOUT THE MISSION. MINOR TRANSVERSE BANDING IS CONTINUOUS THROUGHOUT THE MISSION.

E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS.

3. POSITIVE:

A. PI SUITABILITY IS GOOD. PRINTING AND PROCESSING ARE GOOD.

B. CLOUDS OBSCURE OR IMPAIR APPROXIMATELY 50 PERCENT OF THIS MISSION.

1

END OF MESSAGE